

The last flight of *Texas* *Tornado*

Robert Brassey
Principal Specialist Cultural Heritage





Flying fortress crash site



USAAF B17E Flying Fortress 9 June 1942

- In NZ on secret mission
- Crashed soon after take-off at night
- Caught fire on impact, 500lb bomb exploded, then 26,000 litres of fuel
- All 11 occupants killed, neighbouring house/farm buildings severely damaged
- Casualties buried at Waikumete Cemetery and remains repatriated post-war
- Large wreckage removed, rest bulldozed into bomb crater [eye witness]



Crash site management

- Site apparently undisturbed but development imminent
- Previous reports of finds of human remains & munitions (post clearance) at site
- Protection by scheduling not feasible
- Negotiated consent conditions providing for prior investigation/monitoring before development
- Located archaeologists willing to lead project voluntarily. Owners contributed machinery & other support. Team of ca 15 volunteers did work
- Liaison with current owner (NZRPG), US Consul, US Defense MIA Unit, Ministry for Cultural Heritage, Auckland Museum, NZ Air Force, Local Board....

Objectives

- Locate and undertake a controlled excavation of infilled bomb crater to allow identification and recovery of any further human remains, personal items or definitive crash relics
- Determine if any unexploded ordnance or contaminants present
- Make a record of the site before it was destroyed



Infilled crater located by ortho-rectification of aerials, probing and test pitting



Artefacts

- Top of crater fill – artefacts associated with crash clean-up; damaged farm/house items (fencing, roofing, tree limbs etc)
- Numerous aircraft components. Duralumin (structural aluminium alloy) badly corroded, some melted.
- Rubber & fabric items (incl 'Mae West' lifejackets), ?seat material.
- Many small items, buckles etc.



Sealed bottle
Iodine from
Med kit?



Ammunition – lots, but all had exploded during the fire

Mostly heavy machine gun;
also light machine gun & side
arm calibres





Bullet/puncture
-proof rubber
fuel tank (burnt
remains)



Personal Items



Lieutenant's Bar
(Navigator?)

Sidearm Holster
(Front Cover) Left?





USAAF Boot Possibly Model A-6A





Bomb Fragments



- Bomb Fragments at bottom of crater
- Number engraved '..36B6'
- Possible model AN/M43?



Crew loading 500lb bombs in Australia 1942



Finished



9/5/2017

Outcomes of site investigation

- No human remains found during excavation. All earlier reported finds followed up to check if any locatable
- Contamination not significant, but strong fuel smell in base of crater
- Personal/uniform items to be repatriated to US MIA unit
- In discussion with Auckland Museum regarding other items
- Analysis/report in prep. (by volunteers)
- Land owner receptive to memorializing event at/near site
- Open days and TV1 News item, conference poster
- Site of tragedy treated with respect and in accordance with wishes of US Consul & Defense Dept.
- Very positive feedback, including from owner
- No cost to Auckland Council other than some staff time - several HU staff worked voluntarily

Crash site investigation was about doing what was right rather than what we were required to do. No agency has any responsibility for such sites

Cause of the crash

- Aircraft reached an altitude of around 150' (50 m) then began to descend and struck rising ground before coming to rest around 2.6 km beyond the end of the runway
- Outcome of inquiry: pilot error. Contributing factors: changeover from flying by landing lights to instrument flying; lack of familiarity with terrain
- Board of inquiry was unfamiliar with aircraft & its controls

Cause of the crash

Aircraft: Well regarded and capable aircraft. No evidence any faults contributed to crash

Environment: Night, but fine and clear conditions

Pilot: Very experienced, had landed at Whenuapai recently, inspected runway the day before

but....

Cause of the crash

- Pilot and co-pilot had spent the evening socializing in the Grand Hotel, Princes Street. Arrived in taxis with women at midnight
- *They...had been enjoying themselves, although they were still perfectly capable of flying the machine* (eye witness)
- Took off without undertaking pre-flight checks. Did not test control surfaces (ailerons, elevator, rudder)

Cause of the crash

- Complex aircraft to fly
- Prototype of B17 crashed due to failure to disengage gust locks
- Can be difficult or impossible to disengage after take-off and situation may not become apparent until too late
- Written pre-flight checklists introduced



APPROVED B-17F and G CHECKLIST	
SERIES 2-1-44	
PILOT'S DUTIES IN RED	
COPILOT'S DUTIES IN BLACK	
BEFORE STARTING	ENGINE RUN-UP
1. Pilot's Profile— COMPLETE	1. Brakes— Locked
2. Fuel— OK—CHECKED	2. Trim Tab— SET
3. Controls and Seats— CHECKED	3. Starter Turbine and Props
4. Fuel Transfer Valves & Switch— OFF	4. Check Generators— CHECKED & OFF
5. Intercooler— Cold	5. Run up Engines
6. Dyes— UNCHECKED	
7. Fuel Shut-off Switches— OPEN	BEFORE TAKEOFF
8. Gear Switch— NEUTRAL	1. Tailhook— Locked
9. Cowl Flaps— Open Right— OPEN LEFT—Locked	2. Open— Set
10. Tailhook— OFF	3. Generators— ON
11. Air Intake— CHECKED	
12. Throttle— CLOSED	AFTER TAKEOFF
13. High RPM— CHECKED	1. Wheel— PILOT'S SIGNAL
14. Autopilot— OFF	2. Power Reduction
15. Doors and Aft-ers, Wing and Prop— OFF	3. Cowl Flaps
16. Cabin Heat— OFF	4. Wheel Check— OK right—OK LEFT
17. Generators— OFF	
STARTING ENGINES	BEFORE LANDING
1. Fire Guard and Coil Clear— LEFT Right	1. Radio Call, Altimeter— SET
2. Master Switch— ON	2. Crew Positions— OK
3. Battery switches and Inverters— ON & CHECKED	3. Autopilot— OFF
4. Parking Brake—Hydraulic Check— ON CHECKED	4. Starter Pumps— On
5. Starter Pumps—Pressure— OK & CHECKED	5. Weather Controls— AUTO-SEN
6. Carburetor Filters— Open	6. Intercooler— Set
7. Fuel Quantity—Gallons per tank	7. Carburetor Filters— Open
8. Start Engines— Start magnets on after one revolution	8. Wing Doors— OFF
9. Flight Indicators & Vacuum Pressure CHECKED	9. Landing Gear
10. Radio— On	a. Visual— Down Right—DOWN LEFT
11. Check Instruments— CHECKED	b. Tailhook Down, Antenna in, Bell Turret Checked
12. Crew Report	c. Light— OK
13. Radio Call & Altimeter— SET	d. Switch Off— Neutral
	e. Hydraulic Pressure— OK Valve closed
	f. RPM 1100— Set
	g. Turbine— Set
	h. Flaps 1/2— Down
	FINAL APPROACH
	14. Flaps— PILOT'S SIGNAL
	15. RPM 1200— PILOT'S SIGNAL

Conclusions

- Cause of the crash unable to be determined. Alcohol likely a factor, but needs to be viewed in context – wartime, different standards prevalent then
- No evidence of alcohol on board as later suggested
- Crash investigations were not as rigorous, complicated by status of aircraft
- Surprisingly inconsistent evidence from witnesses
- Possible that there are additional crash remains at the site or in the landfill



Memorial at similar crash site in Arkansas – full size replica, wall of remembrance, shrine...

Acknowledgements

Simon Bickler and Simon Best and numerous other volunteers who contributed many hours of their time and expertise

Mark Gunton, Derek Manning, NZ Retail Property Group for providing logistical support and for being supportive of the investigation

Melanie Higgans US Consul; Jesse Stephen US Defense POW/MIA Accounting Agency for their support and interest